

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Map Symbol And Soil Name	Pct. of Map Unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating Class and Limiting features	Value	Rating Class and Limiting features	Value	Rating Class and Limiting features	Value
AlB:							
Allegheny-----	80	Very limited Low adsorption	1.00	Very limited Restricted permeability	1.00	Very limited Low adsorption	1.00
		Seepage	1.00	Too acid	0.14	Too acid	1.00
		Too acid	1.00	Slope	0.12	Too steep for surface application	0.32
Other Soils-----	20	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
AlC:							
Allegheny-----	80	Very limited Low adsorption	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Seepage	1.00	Restricted permeability	1.00	Too steep for surface application	1.00
		Too acid	1.00	Too acid	0.14	Too acid	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Other Soils-----	20	Too steep for surface application	1.00			Too steep for sprinkler application	1.00
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
An: Atkins-----	35	Very limited Flooding	1.00	Very limited Flooding	1.00	Very limited Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	1.00	Flooding	1.00
		Seepage	1.00			Too acid	1.00
		Too acid	1.00				
Philo-----	30	Very limited Flooding	1.00	Very limited Depth to saturated zone	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00	Depth to bedrock	1.00	Filtering capacity	1.00
		Seepage	1.00	Restricted permeability	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Flooding	0.60	Depth to saturated zone	0.95
		Depth to saturated zone	0.95			Too acid	0.91
Potomac-----	20	Very limited Seepage	1.00	Somewhat limited Cobble content	0.03	Very limited Low adsorption	1.00
		Low adsorption	1.00			Filtering capacity	1.00
		Flooding	0.40				
		Cobble content	0.03				
Other Soils-----	15	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
BaE: Belmont-----	75	Very limited		Very limited		Very limited	

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00	Depth to bedrock	1.00	Too steep for surface application	1.00
		Seepage	1.00	Restricted permeability	1.00	Too steep for sprinkler application	1.00
		Too acid	0.42			Too acid	0.42
		Depth to bedrock	0.42			Depth to bedrock	0.42
Other Soils-----	25	Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
BcC: Berks-----	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Slope	1.00	Too steep for surface application	1.00
		Too acid	0.99	Restricted permeability	0.62	Too acid	0.99
		Too steep for surface application	0.50	Cobble content	0.02	Too steep for sprinkler application	0.50
		Cobble content	0.01			Cobble content	0.32
Other Soils-----	20	Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
BcE: Berks-----	75	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Slope	1.00	Depth to bedrock	1.00
		Too steep for surface application	1.00	Depth to bedrock	1.00	Too steep for surface application	1.00
		Seepage	1.00	Restricted permeability	0.62	Too steep for sprinkler application	1.00
		Too acid	0.99	Cobble content	0.02	Too acid	0.99
		Cobble content	0.01			Cobble content	0.32

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Other Soils-----	25	Very limited Too steep for surface application Low adsorption	1.00 1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Seepage	1.00			Too steep for surface application Too steep for sprinkler application	1.00 1.00
BcF: Berks-----	75	Very limited Depth to bedrock Too steep for surface application Seepage	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Too steep for surface application Too steep for sprinkler application	1.00 1.00 1.00
		Too acid Cobble content	0.99 0.01	Restricted permeability Cobble content	0.62 0.02	Too acid Cobble content	0.99 0.32
Other Soils-----	25	Very limited Too steep for surface application Low adsorption	1.00 1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Seepage	1.00			Too steep for surface application Too steep for sprinkler application	1.00 1.00
BkG: Berks-----	35	Very limited Depth to bedrock Too steep for surface application Seepage	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Too steep for surface application Too steep for sprinkler application	1.00 1.00 1.00
		Too acid Cobble content	0.99 0.01	Restricted permeability Cobble content	0.62 0.02	Too acid Cobble content	0.99 0.32
Weikert-----	25	Very limited Seepage Depth to bedrock	1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Too steep for surface application Too steep for sprinkler application	1.00 1.00 1.00
		Too steep for surface application Too acid	1.00 1.00	Restricted permeability Too acid	0.32 0.14	Too acid	1.00
Calvin-----	20	Very limited Seepage	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Other Soils-----	20	Depth to bedrock	1.00	Depth to bedrock	1.00	Too steep for surface application	1.00
		Too steep for surface application	1.00	Restricted permeability	0.32	Too steep for sprinkler application	1.00
		Too acid	0.91			Too acid	0.91
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
B1C: Berks-----	60	Very limited Depth to bedrock Seepage	1.00 1.00	Very limited Depth to bedrock Slope	1.00 1.00	Very limited Depth to bedrock Too steep for surface application	1.00 1.00
		Too acid	0.99	Restricted permeability	0.62	Too acid	0.99
		Too steep for surface application	0.50	Cobble content	0.02	Too steep for sprinkler application	0.50
		Cobble content	0.01			Cobble content	0.32
Dekalb-----	30	Very limited Seepage Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope	1.00 1.00	Very limited Depth to bedrock Too steep for surface application	1.00 1.00
		Too acid	0.99	Cobble content	0.43	Filtering capacity	1.00
		Too steep for surface application	0.50	Too acid	0.14	Too acid	0.99
		Cobble content	0.41			Too steep for sprinkler application	0.50
Other Soils-----	10	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
B1E: Berks-----	55	Very limited		Very limited		Very limited	

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Dekalb-----	35	Depth to bedrock	1.00	Slope	1.00	Depth to bedrock	1.00
		Too steep for surface application	1.00	Depth to bedrock	1.00	Too steep for surface application	1.00
		Seepage	1.00	Restricted permeability	0.62	Too steep for sprinkler application	1.00
		Too acid	0.99	Cobble content	0.02	Too acid	0.99
		Cobble content	0.01			Cobble content	0.32
		Very limited		Very limited		Very limited	
		Seepage	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Too steep for surface application	1.00
		Too steep for surface application	1.00	Cobble content	0.43	Too steep for sprinkler application	1.00
		Too acid	0.99	Too acid	0.14	Filtering capacity	1.00
Other Soils-----	10	Cobble content	0.49			Too acid	0.99
		Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
BlF: Berks-----	45	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Slope	1.00	Depth to bedrock	1.00
		Too steep for surface application	1.00	Depth to bedrock	1.00	Too steep for surface application	1.00
		Seepage	1.00	Restricted permeability	0.62	Too steep for sprinkler application	1.00
		Too acid	0.99	Cobble content	0.02	Too acid	0.99
		Cobble content	0.01			Cobble content	0.32
		Very limited		Very limited		Very limited	
		Seepage	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Too steep for surface application	1.00
		Too steep for surface application	1.00	Cobble content	0.43	Too steep for sprinkler application	1.00
Dekalb-----	40	Too acid	0.99	Too acid	0.14	Filtering capacity	1.00
		Cobble content	0.41			Too acid	0.99
		Very limited		Very limited		Very limited	
		Seepage	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Too steep for surface application	1.00
Other Soils-----	15	Too steep for surface application	1.00	Cobble content	0.43	Too steep for sprinkler application	1.00
		Seepage	1.00	Restricted permeability	0.62	Too steep for sprinkler application	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
BrE: Berks-----	50	Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
		Very limited Depth to bedrock	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00
		Too steep for surface application	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	0.62	Too steep for surface application	1.00
		Seepage	1.00	Cobble content	0.01	Too steep for sprinkler application	1.00
		Too acid	0.99			Too acid	0.99
		Very limited Seepage	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Too steep for surface application	1.00	Restricted permeability	0.32	Too steep for surface application	1.00
		Low adsorption	1.00			Too steep for sprinkler application	1.00
Weikert-----	35	Too acid	0.91			Too acid	0.91
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00	Depth to bedrock	1.00	Too steep for surface application	1.00
		Seepage	1.00	Restricted permeability	0.32	Too steep for sprinkler application	1.00
Other Soils-----	15	Too acid	0.91			Too acid	0.91
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
BrF: Berks-----	50	Very limited Depth to bedrock	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00
		Too steep for surface application	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	0.62	Too steep for surface application	1.00
		Seepage	1.00	Cobble content	0.01	Too steep for sprinkler application	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Weikert-----	35	Too acid	0.99			Too acid	0.99
		Very limited Seepage	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Too steep for surface application	1.00	Restricted permeability	0.32	Too steep for surface application	1.00
		Low adsorption	1.00			Too steep for sprinkler application	1.00
Other Soils-----	15	Too acid	0.91			Too acid	0.91
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
BtC: Blackthorn-----	75	Very limited Low adsorption	1.00	Very limited Restricted permeability	1.00	Very limited Low adsorption	1.00
		Seepage	1.00	Slope	1.00	Too steep for surface application	1.00
		Too acid	0.91			Large stones on the surface	1.00
		Too steep for surface application	0.50			Too acid	0.91
		Cobble content	0.02			Too steep for sprinkler application	0.50
Other Soils-----	25	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
BtE: Blackthorn-----	75	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	1.00	Too steep for surface application	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Other Soils-----	25	Seepage	1.00			Too steep for sprinkler application	1.00
		Too acid	0.91			Large stones on the surface	1.00
		Cobble content	0.02			Too acid	0.91
		Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
BxF: Briery-----	70	Seepage	1.00			Too steep for sprinkler application	1.00
		Very limited		Very limited		Very limited	
		Low adsorption	1.00	Slope	1.00	Low adsorption	1.00
		Seepage	1.00	Restricted permeability	0.62	Too steep for surface application	1.00
		Too steep for surface application	1.00	Cobble content	0.04	Too steep for sprinkler application	1.00
		Cobble content	0.03				
Other Soils-----	15	Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
Rock Outcrop-----	15	Not rated		Not rated		Not rated	
CbC: Calvin-----	45	Very limited		Very limited		Very limited	
		Seepage	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Slope	1.00	Too steep for surface application	1.00
		Too acid	0.91	Restricted permeability	0.32	Too acid	0.91
		Too steep for surface application	0.50			Too steep for sprinkler application	0.50
Dekalb-----	25	Very limited		Very limited		Very limited	

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Berks-----	20	Seepage	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Slope	1.00	Too steep for surface application	1.00
		Too acid	0.99	Cobble content	0.43	Filtering capacity	1.00
		Too steep for surface application	0.50	Too acid	0.14	Too acid	0.99
		Cobble content	0.41			Too steep for sprinkler application	0.50
		Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Slope	1.00	Too steep for surface application	1.00
		Too acid	0.99	Restricted permeability	0.62	Too acid	0.99
		Too steep for surface application	0.50	Cobble content	0.02	Too steep for sprinkler application	0.50
Other Soils-----	10	Cobble content	0.01			Cobble content	0.32
		Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
CbE: Calvin-----	35	Seepage	1.00			Too steep for sprinkler application	1.00
		Depth to bedrock	1.00				
		Too steep for surface application	1.00	Restricted permeability	0.32	Too steep for sprinkler application	1.00
		Too acid	0.91			Too acid	0.91
Dekalb-----	30	Very limited		Very limited		Very limited	
		Seepage	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Too steep for surface application	1.00
		Too steep for surface application	1.00	Cobble content	0.43	Too steep for sprinkler application	1.00
		Too acid	0.99	Too acid	0.14	Filtering capacity	1.00
		Cobble content	0.41			Too acid	0.99

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Berks-----	20	Very limited Depth to bedrock Too steep for surface application Seepage Too acid Cobble content	1.00 1.00 1.00 0.99 0.01	Very limited Slope Depth to bedrock Restricted permeability Cobble content	1.00 1.00 0.62 0.02	Very limited Depth to bedrock Too steep for surface application Too steep for sprinkler application Too acid Cobble content	1.00 1.00 1.00 0.99 0.32
Other Soils-----	15	Very limited Too steep for surface application Low adsorption Seepage	1.00 1.00 1.00	Very limited Slope	1.00	Very limited Low adsorption Too steep for surface application Too steep for sprinkler application	1.00 1.00 1.00
CbF: Calvin-----	35	Very limited Seepage Depth to bedrock Too steep for surface application Too acid	1.00 1.00 1.00 0.91	Very limited Slope Depth to bedrock Restricted permeability	1.00 1.00 0.32	Very limited Depth to bedrock Too steep for surface application Too steep for sprinkler application Too acid	1.00 1.00 1.00 0.91
Dekalb-----	25	Very limited Seepage Depth to bedrock Too steep for surface application Too acid Cobble content	1.00 1.00 1.00 0.99 0.41	Very limited Slope Depth to bedrock Cobble content Too acid	1.00 1.00 0.43 0.14	Very limited Depth to bedrock Too steep for surface application Too steep for sprinkler application Filtering capacity Too acid	1.00 1.00 1.00 1.00 0.99
Berks-----	20	Very limited Depth to bedrock Too steep for surface application Seepage Too acid Cobble content	1.00 1.00 1.00 0.99 0.02	Very limited Slope Depth to bedrock Restricted permeability Cobble content	1.00 1.00 0.62 0.02	Very limited Depth to bedrock Too steep for surface application Too steep for sprinkler application Too acid Cobble content	1.00 1.00 1.00 0.99 0.32
Other Soils-----	20	Very limited		Very limited		Very limited	

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
CeF: Caneyville-----	40	Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
		Very limited Depth to bedrock	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00
		Too steep for surface application	1.00	Restricted permeability	1.00	Low adsorption	1.00
		Low adsorption	1.00	Depth to bedrock	1.00	Too steep for surface application	1.00
		Seepage	0.62			Too steep for sprinkler application	1.00
		Too acid	0.31			Restricted permeability	0.99
		Very limited Seepage	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Too steep for surface application	1.00	Restricted permeability	1.00	Too steep for surface application	1.00
Frederick-----	30	Low adsorption	1.00			Too steep for sprinkler application	1.00
		Too acid	0.91			Too acid	0.91
Rock Outcrop-----	20	Not rated		Not rated		Not rated	
Other Soils-----	10	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
CfB: Cateache-----	85	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock	1.00
		Low adsorption	1.00	Restricted permeability	1.00	Low adsorption	1.00
		Seepage	1.00	Slope	0.50	Too acid	0.91

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Other Soils-----	15	Too acid	0.91			Too steep for surface application	0.68
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
CfC: Cateache-----	85	Very limited Depth to bedrock	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00
		Low adsorption	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Seepage	1.00	Restricted permeability	1.00	Too steep for surface application	1.00
		Too steep for surface application	1.00			Too steep for sprinkler application	1.00
		Too acid	0.91			Too acid	0.91
Other Soils-----	15	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
CfD: Cateache-----	85	Very limited Depth to bedrock	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00
		Too steep for surface application	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	1.00	Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
		Too acid	0.91			Too acid	0.91
Other Soils-----	15	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
CfE: Cateache-----	85	Seepage	1.00			Too steep for sprinkler application	1.00
		Very limited Depth to bedrock	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00
		Too steep for surface application	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	1.00	Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
Other Soils-----	15	Too acid	0.91			Too acid	0.91
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
CfF: Cateache-----	85	Very limited Depth to bedrock	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00
		Too steep for surface application	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	1.00	Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
		Too acid	0.91			Too acid	0.91
Other Soils-----	15	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
CgC: Cateache-----	85	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock	1.00
		Low adsorption	1.00	Restricted permeability	1.00	Low adsorption	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
		Seepage	1.00	Slope	1.00	Too steep for surface application	1.00
		Too acid	0.91			Too acid	0.91
		Too steep for surface application	0.50			Too steep for sprinkler application	0.50
Other Soils-----	15	Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
CgE: Cateache-----	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Slope	1.00	Depth to bedrock	1.00
		Too steep for surface application	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	1.00	Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
		Too acid	0.91			Too acid	0.91
Other Soils-----	15	Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
CgF: Cateache-----	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Slope	1.00	Depth to bedrock	1.00
		Too steep for surface application	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	1.00	Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
		Too acid	0.91			Too acid	0.91
Other Soils-----	15	Very limited		Very limited		Very limited	

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Ch: Chavies-----	85	Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
		Very limited Seepage	1.00			Very limited Low adsorption	1.00
		Low adsorption	1.00			Too acid	0.31
		Flooding	0.40				
		Too acid	0.31				
		Very limited Too steep for surface application	1.00			Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
CpB: Cookport-----	80	Very limited Low adsorption	1.00	Very limited Restricted permeability	1.00	Very limited Low adsorption	1.00
		Seepage	1.00			Too acid	1.00
		Too acid	1.00			Depth to saturated zone	1.00
		Depth to saturated zone	1.00			Depth to saturated zone	1.00
		Depth to bedrock	0.05			Restricted permeability	0.96
						Too steep for surface application	0.50
		Very limited Too steep for surface application	1.00			Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
CuB: Culleoka-----	90	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock	1.00
		Low adsorption	1.00			Low adsorption	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Other Soils-----	10	Seepage	1.00	Slope	0.28	Too acid	0.67
		Too acid	0.67			Too steep for surface application	0.50
		Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
CuC: Culleoka-----	85	Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
		Seepage	1.00				
		Very limited		Very limited		Very limited	
Other Soils-----	15	Depth to bedrock	1.00	Slope	1.00	Depth to bedrock	1.00
		Low adsorption	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Seepage	1.00	Restricted permeability	0.62	Too steep for surface application	1.00
		Too steep for surface application	1.00			Too steep for sprinkler application	1.00
CuD: Culleoka-----	85	Too acid	0.67			Too acid	0.67
		Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Slope	1.00	Depth to bedrock	1.00
		Too steep for surface application	1.00	Depth to bedrock	1.00	Low adsorption	1.00
Other Soils-----	15	Low adsorption	1.00	Restricted permeability	0.62	Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
		Too acid	0.67			Too acid	0.67
		Very limited		Very limited		Very limited	
Other Soils-----	15	Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
CyE: Culleoka-----	80	Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
		Very limited Depth to bedrock	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00
		Too steep for surface application	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	0.62	Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
		Too acid	0.67			Too acid	0.67
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
CyF: Culleoka-----	75	Very limited Depth to bedrock	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00
		Too steep for surface application	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	0.62	Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
		Too acid	0.67			Too acid	0.67
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
		Too acid	0.67			Too acid	0.67
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
DeC: Dekalb-----	75	Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
		Very limited Depth to bedrock	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00
		Too steep for surface application	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	0.62	Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
		Too acid	0.67			Too acid	0.67
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Other Soils-----	25	Seepage	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00	Cobble content	0.47	Too steep for surface application	1.00
		Too acid	0.99	Too acid	0.14	Filtering capacity	1.00
		Too steep for surface application	0.50			Too acid	0.99
		Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
DeE: Dekalb-----	75	Very limited		Very limited		Very limited	
		Seepage	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Too steep for surface application	1.00	Cobble content	0.47	Too steep for surface application	1.00
		Low adsorption	1.00	Too acid	0.14	Too steep for sprinkler application	1.00
		Too acid	0.99			Filtering capacity	1.00
Other Soils-----	25	Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
DeF: Dekalb-----	75	Very limited		Very limited		Very limited	
		Seepage	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Too steep for surface application	1.00	Cobble content	0.47	Too steep for surface application	1.00
		Low adsorption	1.00	Too acid	0.14	Too steep for sprinkler application	1.00
		Too acid	0.99			Filtering capacity	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Other Soils-----	25	Very limited Too steep for surface application Low adsorption	1.00 1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Seepage	1.00			Too steep for surface application Too steep for sprinkler application	1.00 1.00
DhC: Dekalb-----	55	Very limited Seepage Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope	1.00 1.00	Very limited Depth to bedrock Too steep for surface application Filtering capacity Too acid	1.00 1.00 1.00 0.99
		Too acid Too steep for surface application Cobble content	0.99 0.50 0.41	Cobble content Too acid	0.43 0.14	Too steep for sprinkler application	0.50
Hazleton-----	35	Very limited Seepage Too acid	1.00 1.00	Very limited Depth to bedrock Slope	1.00 1.00	Very limited Too acid Too steep for surface application Depth to bedrock Too steep for sprinkler application	1.00 1.00 1.00 0.50
		Depth to bedrock Cobble content	1.00 0.51	Cobble content Restricted permeability	0.52 0.32		
		Too steep for surface application	0.50	Too acid	0.14		
Other Soils-----	10	Very limited Too steep for surface application Low adsorption	1.00 1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Seepage	1.00			Too steep for surface application Too steep for sprinkler application	1.00 1.00
DhE: Dekalb-----	55	Very limited Seepage Depth to bedrock	1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Too steep for surface application Too steep for sprinkler application	1.00 1.00 1.00
		Too steep for surface application	1.00	Cobble content	0.43		

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Hazleton-----	35	Too acid	0.99	Too acid	0.14	Filtering capacity	1.00
		Cobble content	0.41			Too acid	0.99
		Very limited Seepage	1.00	Very limited Slope	1.00	Very limited Too steep for surface application	1.00
		Too steep for surface application	1.00	Depth to bedrock	1.00	Too steep for sprinkler application	1.00
		Too acid	1.00	Cobble content	0.52	Too acid	1.00
		Depth to bedrock	1.00	Restricted permeability	0.32	Depth to bedrock	1.00
Other Soils-----	10	Cobble content	0.51	Too acid	0.14		
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
DhF: Dekalb-----	55	Very limited Seepage	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Too steep for surface application	1.00
		Too steep for surface application	1.00	Cobble content	0.43	Too steep for sprinkler application	1.00
		Too acid	0.99	Too acid	0.14	Filtering capacity	1.00
		Cobble content	0.41			Too acid	0.99
Hazleton-----	35	Very limited Seepage	1.00	Very limited Slope	1.00	Very limited Too steep for surface application	1.00
		Too steep for surface application	1.00	Depth to bedrock	1.00	Too steep for sprinkler application	1.00
		Too acid	1.00	Cobble content	0.52	Too acid	1.00
		Depth to bedrock	1.00	Restricted permeability	0.32	Depth to bedrock	1.00
		Cobble content	0.51	Too acid	0.14		
Other Soils-----	10	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
DkF: Dekalb-----	45	Seepage	1.00			Too steep for sprinkler application	1.00
		Very limited		Very limited		Very limited	
		Seepage	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Too steep for surface application	1.00	Cobble content	0.47	Too steep for surface application	1.00
		Low adsorption	1.00	Too acid	0.14	Too steep for sprinkler application	1.00
		Too acid	0.99			Filtering capacity	1.00
Rock Outcrop-----	40	Not rated		Not rated		Not rated	
Other Soils-----	15	Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
Du: Dunning-----	85	Very limited		Very limited		Very limited	
		Flooding	1.00	Restricted permeability	1.00	Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Low adsorption	1.00
		Low adsorption	1.00	Flooding	0.60	Restricted permeability Flooding	0.96
Other Soils-----	15	Seepage	1.00				0.60
		Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
Elf: Elliber-----	80	Seepage	1.00			Too steep for sprinkler application	1.00
		Very limited		Very limited		Very limited	

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Other Soils-----	20	Too steep for surface application	1.00	Slope	1.00	Too steep for surface application	1.00
		Seepage	1.00	Cobble content	0.72	Too steep for sprinkler application	1.00
		Too acid	1.00	Restricted permeability	0.62	Too acid	1.00
		Cobble content	0.60	Too acid	0.14		
		Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
ErB: Ernest-----	80	Very limited		Very limited		Very limited	
		Low adsorption	1.00	Restricted permeability	1.00	Low adsorption	1.00
		Seepage	1.00	Depth to saturated zone	1.00	Depth to saturated zone	0.95
		Depth to saturated zone	0.95	Slope	0.50	Too acid	0.91
		Too acid	0.91			Too steep for surface application	0.68
						Restricted permeability	0.50
Other Soils-----	20	Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
EsC: Ernest-----	75	Very limited		Very limited		Very limited	
		Low adsorption	1.00	Restricted permeability	1.00	Cobble content	1.00
		Seepage	1.00	Depth to saturated zone	1.00	Low adsorption	1.00
		Too acid	1.00	Slope	1.00	Too steep for surface application	1.00
		Depth to saturated zone	0.95			Too acid	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Other Soils-----	25	Too steep for surface application	0.50			Restricted permeability	0.96
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
FaE: Faywood-----	75	Very limited Depth to bedrock	1.00	Very limited Slope	1.00	Very limited Restricted permeability	1.00
		Too steep for surface application	1.00	Restricted permeability	1.00	Depth to bedrock	1.00
		Low adsorption	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Seepage	1.00			Too steep for surface application	1.00
						Too steep for sprinkler application	1.00
Other Soils-----	25	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
FaF: Faywood-----	75	Very limited Depth to bedrock	1.00	Very limited Slope	1.00	Very limited Restricted permeability	1.00
		Too steep for surface application	1.00	Restricted permeability	1.00	Depth to bedrock	1.00
		Low adsorption	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Seepage	1.00			Too steep for surface application	1.00
						Too steep for sprinkler application	1.00
Other Soils-----	25	Very limited		Very limited		Very limited	

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
FkB: Frankstown-----	75	Very limited		Very limited		Very limited	
		Low adsorption	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Seepage	1.00	Restricted permeability	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Slope	0.50	Too steep for surface application	0.68
		Too acid	0.67			Too acid	0.67
Other Soils-----	25	Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
FkC: Frankstown-----	75	Very limited		Very limited		Very limited	
		Low adsorption	1.00	Slope	1.00	Low adsorption	1.00
		Seepage	1.00	Depth to bedrock	1.00	Too steep for surface application	1.00
		Too steep for surface application	1.00	Restricted permeability	1.00	Too steep for sprinkler application	1.00
		Depth to bedrock	1.00			Depth to bedrock	1.00
		Too acid	0.67			Too acid	0.67
Other Soils-----	25	Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
FkD: Frankstown-----	75	Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Other Soils-----	25	Low adsorption	1.00	Depth to bedrock	1.00	Too steep for surface application	1.00
		Seepage	1.00	Restricted permeability	1.00	Too steep for sprinkler application	1.00
		Depth to bedrock Too acid	1.00 0.67			Depth to bedrock Too acid	1.00 0.67
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
FoC: Frankstown-----	75	Seepage	1.00			Too steep for sprinkler application	1.00
		Depth to bedrock Too acid	1.00 0.67				
		Too steep for surface application	0.50				
Other Soils-----	25	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
						Too steep for sprinkler application	1.00
		Seepage	1.00				
FoE: Frankstown-----	75	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00	Depth to bedrock	1.00	Too steep for surface application	1.00
						Too steep for sprinkler application	1.00
		Seepage	1.00	Restricted permeability	1.00	Depth to bedrock	1.00
		Depth to bedrock Too acid	1.00 0.67			Too acid	1.00 0.67
Other Soils-----	25	Very limited		Very limited		Very limited	

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
FrB: Frederick-----	80	Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
		Very limited Seepage	1.00			Very limited Low adsorption	1.00
		Low adsorption	1.00			Too acid	0.91
		Too acid	0.91			Too steep for surface application	0.68
Other Soils-----	20	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
FrC: Frederick-----	80	Very limited Seepage	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Too steep for surface application	1.00			Too steep for sprinkler application	1.00
		Too acid	0.91			Too acid	0.91
Other Soils-----	20	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
FrD: Frederick-----	80	Very limited Seepage	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Too steep for surface application	1.00			Too steep for surface application	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Other Soils-----	20	Low adsorption	1.00			Too steep for sprinkler application	1.00
		Too acid	0.91			Too acid	0.91
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
FyC: Frederick-----	45	Very limited Seepage	1.00	Very limited Restricted permeability	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00	Slope	1.00	Too steep for surface application	1.00
		Too acid	0.91			Too acid	0.91
		Too steep for surface application	0.50			Too steep for sprinkler application	0.50
Caneyville-----	35	Very limited Seepage	1.00	Very limited Restricted permeability	1.00	Very limited Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Too steep for surface application	1.00
		Too steep for surface application	0.50	Slope	1.00	Too steep for sprinkler application	0.50
		Too acid	0.07			Restricted permeability	0.21
						Too acid	0.07
Other Soils-----	20	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
FyE: Other Soils-----	20	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Frederick-----	40	Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
		Very limited Seepage	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Too steep for surface application	1.00	Restricted permeability	1.00	Too steep for surface application	1.00
		Low adsorption	1.00			Too steep for sprinkler application	1.00
		Too acid	0.91			Too acid	0.91
Caneyville-----	40	Very limited Depth to bedrock	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00
		Too steep for surface application	1.00	Restricted permeability	1.00	Low adsorption	1.00
		Low adsorption	1.00	Depth to bedrock	1.00	Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
		Too acid	0.31			Restricted permeability	0.99
GaC: Gauley-----	85	Very limited Seepage	1.00	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock	1.00
		Depth to bedrock	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00	Cobble content	0.94	Cobble content	1.00
		Too acid	1.00	Restricted permeability	0.32	Too acid	1.00
		Cobble content	0.89	Too acid	0.14	Too steep for surface application	1.00
Other Soils-----	15	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
GaE: Gauley-----	80	Very limited Seepage	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Low adsorption	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Other Soils-----	20	Too steep for surface application	1.00	Cobble content	0.94	Too steep for surface application	1.00
		Low adsorption	1.00	Restricted permeability	0.32	Too steep for sprinkler application	1.00
		Too acid	1.00	Too acid	0.14	Cobble content	1.00
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
GnC: Gilpin-----	75	Very limited Depth to bedrock	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00
		Low adsorption	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Seepage	1.00	Restricted permeability	1.00	Too steep for surface application	1.00
		Too acid	1.00	Too acid	0.14	Too acid	1.00
		Too steep for surface application	1.00			Too steep for sprinkler application	1.00
Other Soils-----	25	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
GnD: Gilpin-----	75	Very limited Depth to bedrock	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00
		Too steep for surface application	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	1.00	Too steep for surface application	1.00
		Seepage	1.00	Too acid	0.14	Too steep for sprinkler application	1.00
		Too acid	1.00			Too acid	1.00
Other Soils-----	25	Very limited		Very limited		Very limited	

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
GpC: Gilpin-----	75	Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
		Very limited Depth to bedrock	1.00	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock	1.00
		Low adsorption	1.00	Restricted permeability	1.00	Low adsorption	1.00
		Seepage	1.00	Slope	1.00	Too acid	1.00
		Too acid	1.00	Too acid	0.14	Too steep for surface application	1.00
		Too steep for surface application	0.50	Cobble content	0.01	Too steep for sprinkler application	0.50
Other Soils-----	25	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
GpE: Gilpin-----	75	Very limited Depth to bedrock	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00
		Too steep for surface application	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	1.00	Too steep for surface application	1.00
		Seepage	1.00	Too acid	0.14	Too steep for sprinkler application	1.00
		Too acid	1.00	Cobble content	0.01	Too acid	1.00
Other Soils-----	25	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Ho: Holly-----	90	Very limited Flooding	1.00	Very limited Flooding	1.00	Very limited Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	1.00	Flooding	1.00
		Seepage	1.00				
Other Soils-----	10	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
KxF: Kaymine-----	70	Very limited Low adsorption	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Seepage	1.00	Restricted permeability	0.62	Too steep for surface application	1.00
		Too steep for surface application	1.00	Cobble content	0.08	Too steep for sprinkler application	1.00
		Cobble content	0.11			Cobble content	0.32
Other Soils-----	15	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
Rock Outcrop-----	15	Not rated		Not rated		Not rated	
LcC: Leatherbark-----	85	Very limited Depth to saturated zone	1.00	Very limited Restricted permeability	1.00	Very limited Depth to saturated zone	1.00
		Low adsorption	1.00	Depth to saturated zone	1.00	Low adsorption	1.00
		Too acid	1.00	Slope	1.00	Too acid	1.00
		Seepage	1.00	Too acid	0.14	Too steep for surface application	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Other Soils-----	15	Too steep for surface application	0.22			Restricted permeability	0.99
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
LgB: Lily-----	85	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock	1.00
		Low adsorption	1.00	Restricted permeability	0.62	Low adsorption	1.00
		Seepage	1.00	Slope	0.50	Too acid	1.00
		Too acid	1.00	Too acid	0.14	Too steep for surface application	0.68
Other Soils-----	15	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
LgC: Lily-----	85	Very limited Depth to bedrock	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00
		Low adsorption	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Seepage	1.00	Restricted permeability	0.62	Too steep for surface application	1.00
		Too acid	1.00	Too acid	0.14	Too acid	1.00
		Too steep for surface application	1.00			Too steep for sprinkler application	1.00
Other Soils-----	15	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
LhE: Lily-----	80	Very limited Depth to bedrock Too steep for surface application Low adsorption	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Low adsorption	1.00 1.00
		Seepage	1.00	Restricted permeability	0.62	Too steep for surface application	1.00
		Too acid	1.00	Too acid	0.14	Too steep for sprinkler application Too acid	1.00 1.00
Other Soils-----	20	Very limited Too steep for surface application Low adsorption	1.00 1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Seepage	1.00			Too steep for surface application Too steep for sprinkler application	1.00 1.00
Lo: Lobdell-----	75	Very limited Flooding Low adsorption	1.00 1.00	Very limited Depth to saturated zone Restricted permeability Flooding	1.00 1.00 0.60	Very limited Low adsorption Depth to saturated zone Flooding Too acid	1.00 0.68 0.60 0.07
		Seepage Depth to saturated zone Too acid	1.00 0.68 0.07				
Other Soils-----	25	Very limited Too steep for surface application Low adsorption	1.00 1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Seepage	1.00			Too steep for surface application Too steep for sprinkler application	1.00 1.00
MaB: Macove-----	85	Very limited Seepage Stone content	1.00 0.94	Very limited Stone content Cobble content	1.00 0.99	Somewhat limited Too acid Too steep for surface application	0.91 0.68
		Too acid Cobble content	0.91 0.31	Slope Restricted permeability	0.50 0.32		
Other Soils-----	15	Very limited		Very limited		Very limited	

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
MaC: Macove-----	85	Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
		Very limited Seepage	1.00	Very limited Slope	1.00	Very limited Too steep for surface application	1.00
		Too steep for surface application	1.00	Stone content	1.00	Too steep for sprinkler application	1.00
		Stone content	0.94	Cobble content	0.99	Too acid	0.91
		Too acid	0.91	Restricted permeability	0.32		
		Cobble content	0.31				
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
MaD: Macove-----	80	Seepage	1.00			Too steep for sprinkler application	1.00
		Very limited Seepage	1.00	Very limited Slope	1.00	Very limited Too steep for surface application	1.00
		Too steep for surface application	1.00	Stone content	1.00	Too steep for sprinkler application	1.00
		Stone content	0.94	Cobble content	0.99	Too acid	0.91
		Too acid	0.91	Restricted permeability	0.32		
		Cobble content	0.31				
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
Other Soils-----	20						
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
McC: Macove-----	80	Very limited Seepage	1.00	Very limited Slope	1.00	Very limited Too steep for surface application	1.00
		Too acid	0.91	Stone content	0.70	Too acid	0.91
		Too steep for surface application	0.50	Cobble content	0.55	Too steep for sprinkler application	0.50
		Stone content	0.01	Restricted permeability	0.32		
Other Soils-----	20	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
McE: Macove-----	75	Very limited Seepage	1.00	Very limited Slope	1.00	Very limited Too steep for surface application	1.00
		Too steep for surface application	1.00	Stone content	0.70	Too steep for sprinkler application	1.00
		Too acid	0.91	Cobble content	0.55	Too acid	0.91
		Stone content	0.01	Restricted permeability	0.32		
Other Soils-----	25	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
MeF: Macove-----	55	Very limited Seepage	1.00	Very limited Slope	1.00	Very limited Too steep for surface application	1.00
		Too steep for surface application	1.00	Stone content	0.68	Too steep for sprinkler application	1.00
		Too acid	0.91	Cobble content	0.55	Too acid	0.91
		Stone content	0.01	Restricted permeability	0.32		
Gilpin-----	30	Very limited		Very limited		Very limited	

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Other Soils-----	15	Depth to bedrock	1.00	Slope	1.00	Depth to bedrock	1.00
		Too steep for surface application	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	1.00	Too steep for surface application	1.00
		Seepage	1.00	Too acid	0.14	Too steep for sprinkler application	1.00
		Too acid	1.00	Cobble content	0.01	Too acid	1.00
		Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
MkC: Mandy-----	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Low adsorption	1.00	Restricted permeability	1.00	Low adsorption	1.00
		Seepage	1.00	Slope	1.00	Too acid	1.00
		Too acid	1.00	Too acid	0.14	Too steep for surface application	1.00
		Too steep for surface application	0.50	Cobble content	0.02	Too steep for sprinkler application	0.50
		Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
Other Soils-----	15	Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
		Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Slope	1.00	Depth to bedrock	1.00
		Too steep for surface application	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	1.00	Too steep for surface application	1.00
		Seepage	1.00	Too acid	0.14	Too steep for sprinkler application	1.00
MkE: Mandy-----	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Slope	1.00	Depth to bedrock	1.00
		Too steep for surface application	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	1.00	Too steep for surface application	1.00
		Seepage	1.00	Too acid	0.14	Too steep for sprinkler application	1.00
		Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Slope	1.00	Depth to bedrock	1.00
		Too steep for surface application	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	1.00	Too steep for surface application	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Other Soils-----	20	Too acid	1.00	Cobble content	0.02	Too acid	1.00
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
MkF: Mandy-----	80	Very limited Depth to bedrock	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00
		Too steep for surface application	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	1.00	Too steep for surface application	1.00
		Seepage	1.00	Too acid	0.14	Too steep for sprinkler application	1.00
Other Soils-----	20	Too acid	1.00	Cobble content	0.01	Too acid	1.00
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
MkG: Mandy-----	80	Very limited Depth to bedrock	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00
		Too steep for surface application	1.00	Depth to bedrock	1.00	Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	1.00	Too steep for surface application	1.00
		Seepage	1.00	Too acid	0.14	Too steep for sprinkler application	1.00
Other Soils-----	20	Too acid	1.00	Cobble content	0.01	Too acid	1.00
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
M1: Melvin-----	50	Seepage	1.00			Too steep for sprinkler application	1.00
		Very limited Flooding	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Restricted permeability	1.00	Low adsorption	1.00
		Low adsorption	1.00	Flooding	0.60	Flooding	0.60
		Seepage	1.00				
Lindside-----	35	Very limited Flooding	1.00	Very limited Depth to saturated zone	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	1.00	Depth to saturated zone	0.95
		Seepage	1.00	Flooding	0.60	Flooding	0.60
		Depth to saturated zone	0.95				
Other Soils-----	15	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
MzC: Mertz-----	75	Very limited Seepage	1.00	Very limited Slope	1.00	Very limited Too steep for surface application	1.00
		Too steep for surface application	1.00	Restricted permeability	1.00	Too steep for sprinkler application	1.00
		Too acid	0.07			Restricted permeability	0.26
						Too acid	0.07
Other Soils-----	25	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
MzE: Mertz-----	75	Very limited		Very limited		Very limited	

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
		Too steep for surface application	1.00	Slope	1.00	Too steep for surface application	1.00
		Seepage	1.00	Restricted permeability	1.00	Too steep for sprinkler application	1.00
		Too acid	0.07			Restricted permeability	0.26
						Too acid	0.07
Other Soils-----	25	Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
No: Nolin-----	80	Very limited		Very limited		Somewhat limited	
		Flooding	1.00	Depth to saturated zone	1.00	Flooding	0.60
		Seepage	1.00	Restricted permeability	1.00		
				Flooding	0.60		
Other Soils-----	20	Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
Ph: Philo-----	75	Very limited		Very limited		Very limited	
		Flooding	1.00	Depth to saturated zone	1.00	Low adsorption	1.00
		Low adsorption	1.00	Depth to bedrock	1.00	Filtering capacity	1.00
		Seepage	1.00	Restricted permeability	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Flooding	0.60	Depth to saturated zone	0.95
		Depth to saturated zone	0.95			Too acid	0.91
Other Soils-----	25	Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Po: Pope-----	75	Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
		Very limited Flooding	1.00	Somewhat limited Restricted permeability	0.62	Very limited Low adsorption	1.00
		Seepage	1.00	Flooding	0.60	Too acid	1.00
		Low adsorption	1.00	Too acid	0.14	Flooding	0.60
		Too acid	1.00				
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
Pt: Potomac-----	80	Very limited Seepage	1.00	Somewhat limited Cobble content	0.03	Very limited Low adsorption	1.00
		Low adsorption	1.00			Filtering capacity	1.00
		Flooding	0.40				
		Cobble content	0.03				
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
PuA: Purdy-----	80	Very limited Depth to saturated zone	1.00	Very limited Restricted permeability	1.00	Very limited Depth to saturated zone	1.00
		Low adsorption	1.00	Depth to saturated zone	1.00	Low adsorption	1.00
		Too acid	1.00	Too acid	0.14	Too acid	1.00
		Seepage	0.62			Restricted permeability	0.96
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
Qu: Quarry-----	80	Not rated		Not rated		Not rated	
Other Soils-----	20	Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
Se: Sensabaugh-----	80	Very limited		Very limited		Very limited	
		Flooding	1.00	Depth to saturated zone	1.00	Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	0.62	Flooding	0.60
		Seepage	1.00	Flooding	0.60		
Other Soils-----	20	Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
SfB: Shouns-----	85	Very limited		Very limited		Very limited	
		Low adsorption	1.00	Restricted permeability	1.00	Low adsorption	1.00
		Seepage	1.00	Slope	0.50	Too steep for surface application	0.68
		Too acid	0.67			Too acid	0.67
Other Soils-----	15	Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
SfC: Shouns-----	85	Very limited Low adsorption Seepage	1.00 1.00	Very limited Slope Restricted permeability	1.00 1.00	Very limited Low adsorption Too steep for surface application	1.00 1.00
		Too steep for surface application	1.00			Too steep for sprinkler application	1.00
		Too acid	0.67			Too acid	0.67
Other Soils-----	15	Very limited Too steep for surface application Low adsorption	1.00 1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Seepage	1.00			Too steep for surface application	1.00
						Too steep for sprinkler application	1.00
ShC: Shouns-----	80	Very limited Low adsorption Seepage	1.00 1.00	Very limited Restricted permeability Slope	1.00 1.00	Very limited Low adsorption Too steep for surface application	1.00 1.00
		Too acid	0.67			Large stones on the surface	1.00
		Too steep for surface application	0.50			Too acid	0.67
						Too steep for sprinkler application	0.50
Other Soils-----	20	Very limited Too steep for surface application Low adsorption	1.00 1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Seepage	1.00			Too steep for surface application	1.00
						Too steep for sprinkler application	1.00
ShE: Shouns-----	75	Very limited		Very limited		Very limited	

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	1.00	Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
		Too acid	0.67			Large stones on the surface	1.00
						Too acid	0.67
Other Soils-----	25	Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
ShF: Shouns-----	75	Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	1.00	Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
		Too acid	0.67			Large stones on the surface	1.00
						Too acid	0.67
Other Soils-----	25	Very limited		Very limited		Very limited	
		Too steep for surface application	1.00	Slope	1.00	Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
SmC: Simoda-----	75	Very limited		Very limited		Very limited	
		Low adsorption	1.00	Restricted permeability	1.00	Low adsorption	1.00
		Seepage	1.00	Depth to saturated zone	1.00	Too acid	1.00
		Too acid	1.00	Depth to bedrock	1.00	Cobble content	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Other Soils-----	25	Depth to saturated zone	1.00	Slope	1.00	Too steep for surface application	1.00
		Too steep for surface application	0.50	Too acid	0.14	Depth to saturated zone	1.00
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
SoC: Snowdog-----	75	Very limited Low adsorption	1.00	Very limited Restricted permeability	1.00	Very limited Low adsorption	1.00
		Seepage	1.00	Depth to saturated zone	1.00	Too acid	1.00
		Too acid	1.00	Slope	1.00	Too steep for surface application	1.00
		Depth to saturated zone	1.00	Stone content	0.15	Large stones on the surface	1.00
		Too steep for surface application	0.50	Too acid	0.14	Depth to saturated zone	1.00
Other Soils-----	25	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
SoE: Snowdog-----	75	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00	Restricted permeability	1.00	Too steep for surface application	1.00
		Seepage	1.00	Depth to saturated zone	1.00	Too steep for sprinkler application	1.00
		Too acid	1.00	Stone content	0.15	Too acid	1.00
		Depth to saturated zone	1.00	Too acid	0.14	Large stones on the surface	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Other Soils-----	25	Very limited Too steep for surface application Low adsorption	1.00 1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Seepage	1.00			Too steep for surface application Too steep for sprinkler application	1.00 1.00
SoF: Snowdog-----	75	Very limited Too steep for surface application Low adsorption	1.00 1.00	Very limited Slope Restricted permeability	1.00 1.00	Very limited Low adsorption Too steep for surface application	1.00 1.00
		Seepage	1.00	Depth to saturated zone	1.00	Too steep for sprinkler application	1.00
		Too acid Depth to saturated zone	1.00 1.00	Stone content Too acid	0.15 0.14	Too acid Large stones on the surface	1.00 1.00
Other Soils-----	25	Very limited Too steep for surface application Low adsorption	1.00 1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Seepage	1.00			Too steep for surface application Too steep for sprinkler application	1.00 1.00
SvC: Summers-----	75	Very limited Seepage	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to bedrock	1.00
		Depth to bedrock Low adsorption	1.00 1.00	Depth to bedrock Slope	1.00 1.00	Low adsorption Too steep for surface application	1.00 1.00
		Too acid Too steep for surface application	1.00 0.22			Too acid Too steep for sprinkler application	1.00 0.22
Other Soils-----	25	Very limited Too steep for surface application Low adsorption	1.00 1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
						Too steep for surface application	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Tp: Tioga-----	55	Seepage	1.00			Too steep for sprinkler application	1.00
		Very limited Flooding	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Flooding	0.60
		Seepage	1.00	Restricted permeability	0.62	Too acid	0.07
		Too acid	0.07	Flooding	0.60		
Potomac-----	35	Very limited Seepage	1.00	Somewhat limited Cobble content	0.03	Very limited Low adsorption	1.00
		Low adsorption	1.00			Filtering capacity	1.00
		Flooding	0.40				
Other Soils-----	10	Cobble content	0.03				
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
TrC: Trussel-----	80						
		Very limited Depth to saturated zone	1.00	Very limited Restricted permeability	1.00	Very limited Depth to saturated zone	1.00
		Low adsorption	1.00	Depth to saturated zone	1.00	Low adsorption	1.00
		Seepage	1.00	Slope	1.00	Too acid	1.00
		Too acid	1.00	Too acid	0.14	Too steep for surface application	1.00
						Too steep for sprinkler application	0.50
		Too steep for surface application	0.50				
Other Soils-----	20	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
						Too steep for sprinkler application	1.00
		Seepage	1.00				
Uf: Udlfluvents-----	45	Very limited Low adsorption	1.00	Not limited		Very limited Low adsorption	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
		Seepage	1.00				
Fluvaquents-----	35	Very limited Low adsorption Seepage	1.00 1.00	Not limited		Very limited Low adsorption	1.00
Other Soils-----	20	Very limited Too steep for surface application Low adsorption	1.00 1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Seepage	1.00			Too steep for surface application Too steep for sprinkler application	1.00 1.00
Ux: Other Soils-----	5	Very limited Too steep for surface application Low adsorption	1.00 1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Seepage	1.00			Too steep for surface application Too steep for sprinkler application	1.00 1.00
Udorthents-----	60	Very limited Low adsorption Too steep for surface application Seepage	1.00 1.00 1.00	Very limited Slope	1.00	Very limited Low adsorption Too steep for surface application Too steep for sprinkler application	1.00 1.00 1.00
Rock Outcrop-----	35	Not rated		Not rated		Not rated	
W: Water-----	100	Very limited Very limited Too steep for surface application Too steep for surface application Low adsorption Low adsorption	1.00 1.00 1.00 1.00	Very limited Very limited Slope Slope	1.00 1.00	Very limited Very limited Low adsorption Low adsorption Too steep for surface application Too steep for surface application	1.00 1.00 1.00 1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
		Seepage	1.00			Too steep for sprinkler application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
WeC: Weikert-----	80	Very limited Seepage Depth to bedrock	1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Too steep for surface application	1.00 1.00
		Too steep for surface application Too acid	1.00 0.91	Restricted permeability	0.32	Too steep for sprinkler application Too acid	1.00 0.91
Other Soils-----	20	Very limited Too steep for surface application Low adsorption	1.00 1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Seepage	1.00			Too steep for surface application Too steep for sprinkler application	1.00 1.00
WeD: Weikert-----	75	Very limited Seepage Depth to bedrock	1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Too steep for surface application	1.00 1.00
		Too steep for surface application Too acid	1.00 0.91	Restricted permeability	0.32	Too steep for sprinkler application Too acid	1.00 0.91
Other Soils-----	25	Very limited Too steep for surface application Low adsorption	1.00 1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Seepage	1.00			Too steep for surface application Too steep for sprinkler application	1.00 1.00
WeF: Weikert-----	75	Very limited Seepage Depth to bedrock	1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Too steep for surface application	1.00 1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Other Soils-----	25	Too steep for surface application	1.00	Restricted permeability	0.32	Too steep for sprinkler application	1.00
		Too acid	0.91			Too acid	0.91
		Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
WrG: Other Soils-----	10	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00
Weikert-----	40	Very limited Seepage	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Too steep for surface application	1.00
		Too steep for surface application	1.00	Restricted permeability	0.32	Too steep for sprinkler application	1.00
		Too acid	1.00	Too acid	0.14	Too acid	1.00
Berks-----	35	Very limited Depth to bedrock	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00
		Too steep for surface application	1.00	Depth to bedrock	1.00	Too steep for surface application	1.00
		Seepage	1.00	Restricted permeability	0.62	Too steep for sprinkler application	1.00
		Too acid	0.99	Cobble content	0.02	Too acid	0.99
		Cobble content	0.01			Cobble content	0.32
Rough-----	15	Very limited Seepage	1.00	Very limited Slope	1.00	Very limited Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Too steep for surface application	1.00
		Too steep for surface application	1.00	Too acid	0.42	Too steep for sprinkler application	1.00
		Too acid	1.00			Too acid	1.00

Table AWM-2.--Agricultural Waste Management--Continued

Map symbol and soil name	Pct. of map unit	Overland flow of wastewater		Rapid infiltration of wastewater		Slow rate treatment of wastewater	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
ZoA: Zoar-----	80	Very limited Low adsorption	1.00	Very limited Restricted permeability	1.00	Very limited Low adsorption	1.00
		Seepage	1.00	Depth to saturated zone	1.00	Too acid	1.00
		Too acid	1.00			Depth to saturated zone	1.00
		Depth to saturated zone	1.00			Restricted permeability	0.96
Other Soils-----	20	Very limited Too steep for surface application	1.00	Very limited Slope	1.00	Very limited Low adsorption	1.00
		Low adsorption	1.00			Too steep for surface application	1.00
		Seepage	1.00			Too steep for sprinkler application	1.00